

**The following site is being submitted for inclusion into the GIS registry:**

- To begin, click on cell to the right of, *This is a:*
- Use Tab, ↓ or Pg Down to navigate form. Print & include with file when completed.

This is a:	New Submittal
BRRTS ID (no dashes):	0311180814
Comm # (no dashes):	5395599818
County:	Columbia
Region:	South Central
Site Name:	Coop Country Partners
Street Address:	118 S. Main St.
City:	Poynette
Final Closure Date:	2003-01-03
Closure Conditions:	met
Off-source property contamination?	No
(If yes, attach locational data and deed information on pg. 2)	
Right-of-way contamination?	Yes
Contaminated media:	Groundwater and Soil
GPS Coordinates (meters in the <b>WTM91</b> projection)	
Easting (X):	568355
Northing (Y):	324306
Collection Method:	DNR Web Site
Scale or Resolution:	1:
(1:24,000 scale or finer)	
Prepared by:	D. Swimm
Submitted by:	D. Swimm

Source Property Checklist

- ☒ Final Closure Letter
- ☐ The most recent deed including legal descriptions, for all properties within or partially within the contaminated site boundaries w/ Soil > NR 720 RCL and/or GW > NR 140 ES
- ☐ A certified surveyed map or the relevant section of the recorded plat map for those properties where the legal description in the most recent deed refers to a certified survey map or a recorded plat map
- ☒ Parcel ID for all properties w/ Soil > NR 720 RCL and/or GW > NR 140 ES
- ☒ General Location Map
- ☒ Detailed Location Map showing property boundaries, buildings, MW(s), soil borings and/or potable wells etc for properties w/ Soil > NR 720 RCL and/or GW > NR 140 ES
- ☒ Latest Map(s) showing extent or outline of current GW and/or Soil contamination plume
- ☒ Latest Table of GW and/or Soil results
- ☒ Map showing GW flow direction
- ☒ A table of the previous 4 water level elevation measurements
- ☒ Geologic cross section (if generated as part of the site investigation)
- ☐ Statement signed by RP certifying correctness of legal descriptions
- ☒ ROW Notification



January 3, 2003

Scott Moe  
Coop Country Partners Inc  
935 8th St  
Baraboo, WI 53913

RE: **Final Closure**

**Commerce # 53955-9998-18**      **WDNR BRRTS # 03-11-180814**  
Coop Country Partners, 118 S Main St, Poynette

4,000-gallon diesel, 4,000- and 7,500-gallon unleaded gasoline USTs, and associated piping/dispensers removed during December 1997; 400- and 1,000-gallon leaded gasoline USTs removed during June 1999, and 425-gallon leaded gasoline UST removed during February 2000.

Dear Mr. Moe:

The Wisconsin Department of Commerce (Commerce) has received all items required for closure as stated in the May 7, 2001 conditional closure document. This site is now listed as "closed" on the Commerce database.

It is in your best interest to keep all documentation related to the environmental activities at your site. If residual contamination is encountered in the future, appropriate measures must be implemented to assure that it is managed following all applicable regulations. If future site conditions indicate that any remaining contamination poses a threat, and subsequent information indicates a need to reopen this case, any original claim under the PECFA fund would also reopen and you may apply for assistance to the extent of remaining eligibility.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (608) 264-8766.

Sincerely,

A handwritten signature in dark ink, appearing to read 'D. Swimm'. The signature is fluid and cursive, written over a light background.

David Swimm  
Hydrogeologist  
Site Review Section


cc: William Buckingham, Resource Engineering Associates, Inc.

670942

Document Number

NOTICE OF CONTAMINATION TO  
PROPERTYSTATE OF WISCONSIN } ss  
COLUMBIA COUNTY  
RECEIVED FOR RECORD

NOV 25 2002

  
 Reg of Deeds at 10:10 AM

Legal Description of the Property: In re:

Commencing at the Southeast corner of Lot One (1), Block Ten (10), Jamieson's Addition to the Village of Poynette, Columbia County, Wisconsin, thence Southerly 218 feet on an extension of the East line of said Block Ten (10), thence Westerly parallel with the South line of said Lot One (1) 132 feet, thence Northerly and parallel with the extended Easterly line of said Block Ten (10) 218 feet to the South line of said Block Ten (10) to the place of beginning.

Recording Area

Name and Return Address

Co-op Country Partners  
935 8th  
Baraboo, WI 53913

172-179

Parcel Identification Number (PIN)

STATE OF WISCONSIN )  
 ) ss  
COUNTY OF COLUMBIA )

Section 1. Village of Poynette is the owner of the above-described property.

Section 2. One or more petroleum discharges have occurred at this property. Benzene contaminated groundwater above NR 140 enforcement standards and soils above either NR720/746 direct contact levels or NR 720 residual contaminant levels of the Wisconsin Administrative Code exist(s) on this property in the area of the former underground storage tank (UST) system components.

Section 3. It is the desire and intention of the property owner to impose restrictions on the property, which will make it unnecessary to conduct additional soil or groundwater remediation activities on the property. The owner hereby declares that all of the property described above is held and shall be held, conveyed or encumbered, leased, rented, used, and improved subject to the following limitations and/or restrictions:

Anyone who proposes to construct or reconstruct a well on this property is required to contact the Department of Natural Resources' Bureau of Drinking Water and Groundwater, or its successor agency, to determine what specific prohibitions or requirements are applicable, prior to constructing or reconstructing a well on the property. No well may be constructed or reconstructed on this property unless applicable requirements are met.

Petroleum contaminated soils with concentrations above the NR 746 direct contact standard for benzene remain on this property at the location of the soil boring at CB-1 at a depth of 2-4 feet below ground surface (bgs). This is at or near the location of the former 1,000-gallon leaded gasoline UST. Lead contaminated soils with concentrations above the NR 720 direct contact

standard remain at the location of the soil borings at CB-1, CB-4, CB-6, and B-5 at depths from 1-4 feet bgs. An impermeable cap or cover is the selected remedial action to address residual soil contamination on the property. Therefore, an impermeable cap or cover (ie. asphalt) shall be maintained across this property until: 1). The soil is actively remediated or removed or; 2). It can be shown that the soil has naturally degraded to levels shown to be protective of the environment and human health. If subsurface work is done in the contaminated areas, the contamination shall be properly treated or disposed of in accordance with applicable laws.

Residual petroleum contaminated soil with benzene concentrations as high as 0.078 mg/kg remains on this site in the area of the former UST system components (CB-2, CB-5, and beneath the former southerly gasoline dispenser) at depths from 2 feet bgs to groundwater. It has been shown that these levels are protective of health and the environment. If this contaminated soil is excavated in the future, it may be considered a solid waste and will need to be disposed in accordance with all applicable laws. (File reference: Commerce #53955-9998-18-A, BRRTs #03-11-180814)

Any person who is or becomes owner of the property described above may request that the Wisconsin Department of Commerce, or its successor, issue a determination that the restrictions set forth in this covenant are no longer required. That property owner shall provide any and all necessary information to the Department in order for the Department to be able to make a determination. Upon receipt of such a request, the Department shall determine whether or not the restrictions contained herein can be extinguished. Conditions under which a restriction may be extinguished will be determined in accordance with the site specific standards, rules and laws for this property. If the Department determines that the restrictions can be extinguished, an affidavit, with a copy of the Department's written determination, may be recorded to give notice that this restriction, or portions of this restriction are no longer binding. Any restriction placed upon this property shall not be extinguished without the Department's written determination.

IN WITNESS WHEREOF, the owner of the property has executed this document, this 14<sup>th</sup> day of OCTOBER, 2006.

By signing this document, [he/she] acknowledges that [he/she] is duly authorized to sign this document on behalf of Village of Poynette.

Signature: Herbert G. Werner


Printed Name: Herbert G. Werner

Title: Village President

Subscribed and sworn to before me  
this 14 day of OCT, 2006.

Kathleen Bue  
Notary Public, State of Wisconsin  
My commission July 31, 2006

This document was drafted by the Wisconsin Department of Commerce.



Site is located in the SE 1/4 of the NE 1/4 of Section 34,  
T11N, R9E, Poynette, Columbia County, Wisconsin

Base map from Poynette, Wisconsin 7.5 minute  
USGS topographic quadrangle map (1984)



SCALE: 1" = 2000'

**COOP COUNTRY PARTNERS**

118 South Main Street  
Poynette, Wisconsin

**VICINITY MAP**

May 1998

970094.2

POYNET02.DWG




**RESOURCE  
ENGINEERING  
ASSOCIATES, INC.**

Drawn By: JJC

Checked By: VVB

FIGURE 1




REVISIONS:

Resource Engineering Associates, Inc.  
8505 University Green  
Suite 200  
Middleton, Wisconsin 53552-2507  
P: 608-831-6563 F: 608-831-6564

**REX**  
**ENGINEERING**  
**ASSOCIATES, INC.**

ISO CONCENTRATION MAP  
BENZENE LEVELS IN GROUNDWATER  
COOP COUNTRY PARTNERS  
LUST - REMEDIAL INVESTIGATION  
118 S. Main Street, Poyette, WI

Date: SEPT 1998  
Drawn: SKB  
Checked: BUC  
Approved: WMB  
PROJECT: WMB  
#970094.3  
FIGURE 5



# NOTES

- 1) All dimensions and locations are approximate and are based on aerial photographs and limited field measurements by REX.
- 2) See Figure 1 for site location relative to Poyette, Wisconsin.
- 3) Laboratory analytical data from June 1998 sampling event.
- 4) See Report Appendix for laboratory analytical results.

# LEGEND

- APPROXIMATE LOCATION OF FORMER FUEL DISPENSER ISLANDS (3)
- APPROXIMATE LOCATION OF SOIL BORING ANNULUS USING A RESPONSE BY SOIL ESSENTIALS
- APPROXIMATE LOCATION OF EXISTING GROUNDWATER MONITORING WELL (SHALLOW WELL)
- APPROXIMATE LOCATION OF EXISTING GROUNDWATER PIEZOMETER WELL (DEEP WELL)
- BENZENE CONCENTRATION IDENTIFIED IN GROUNDWATER AT MONITORING WELL SAMPLING POINT (ug/l)
- BENZENE ISO CONCENTRATION CONTOUR LINE (0.1-1 ug/l, 1-10 ug/l and 10-100 ug/l)

## REMEDIAL INVESTIGATION REPORT

Coop Country Partners  
Poynette, Wisconsin

Table 1  
Coop Country Partners - Poynette  
Laboratory Analytical Results - Soils  
7/1/98

Laboratory Parameters (Units)	RCL	B-1 @ 4-8'	B-2 @ 4-8'	B-2 @ 8-12'	B-3 @ 1-4'	B-3 @ 4-8'	B-4 @ 4-8'	B-4 @ 8-12'	B-5 @ 1-4'
Solids (%)	—	86.3	81.1	44.8	84.3	88.6	90.4	80.9	90.7
Lead (mg/kg)	50	127	323	131	16.9	10.2	4.04	3.86	660
DRO (mg/kg)	100	NA	NA	NA	NA	NA	NA	12	NA
GRO (mg/kg)	100	2,200	12	52	6.5	3.4	120	8.6	120
Benzene (ug/kg)	5.5	2,000	<25	<25	<25	<25	<50	310	330
Toluene (ug/kg)	1,500	<1,200	<25	<25	<25	<25	100	<25	550
Ethylbenzene (ug/kg)	2,900	39,000	<25	<25	<25	<25	380	<25	1,000
MTBE (ug/kg)	—	<1,200	<25	<25	<25	<25	<50	<25	140
Xylenes, Total (ug/kg)	4,100	143,300	41	130	51	<50	1,420	830	11,700
1,3,5-TMB (ug/kg)	—	39,000	69	270	32	29	2,900	250	2,600
1,2,4-TMB (ug/kg)	—	93,000	95	360	33	<25	4,900	380	4,400

abbreviations:

ug/kg = micrograms per kilogram = parts per billion (ppb)  
 mg/kg = milligrams per kilogram = parts per million (ppm)  
 TMB = Trimethylbenzene  
 Shading indicates parameter concentration above NR 720 RCL



## REMEDIAL INVESTIGATION REPORT

Coop Country Partners  
Poynette, Wisconsin

Table 1 (Continued)  
Coop Country Partners - Poynette  
Laboratory Analytical Results - Soils  
7/1/98

Laboratory Parameters (Units)	RCL	B-6 @ 4-8'	B-6 @ 8-12'	B-7 @ 4-8'	B-7 @ 8-12'	B-8 @ 4-8'	B-8 @ 8-12'	B-9 @ 4-8'	B-9 @ 8-12'
Solids (%)	—	90.5	70.4	84.1	80.6	91.6	81.3	86.2	88.1
Lead (mg/kg)	50	7.37	70.7	20.7	391	20.8	258	2.34	8.04
DRO (mg/kg)	100	NA	NA	NA	NA	NA	NA	42	80
GRO (mg/kg)	100	4.8	3.6	5,100	400	1,200	34	43	330
Benzene (ug/kg)	5.5	<25	160	8,400	770	<1,200	2,600	45	280
Toluene (ug/kg)	1,500	<25	<25	81,000	2,400	14,000	170	170	1,400
Ethylbenzene (ug/kg)	2,900	57	<25	100,000	10,000	36,000	630	730	6,900
MTBE (ug/kg)	—	<25	<25	9,400	540	<1,200	48	34	<250
Xylenes, Total (ug/kg)	4,100	<50	58	510,000	39,800	154,000	2,550	3,410	31,400
1,3,5-Trimethylbenzene (ug/kg)	—	34	<25	92,000	7,800	32,000	400	840	9,200
1,2,4-Trimethylbenzene (ug/kg)	—	41	82	240,000	22,000	87,000	910	2,300	24,000

## Abbreviations:

ug/kg = micrograms per kilogram = parts per billion (ppb)  
mg/kg = milligrams per kilogram = parts per million (ppm)

Shading indicates parameter concentration above NR 720 RCL

Table 2  
Coop Country Partners - Poynette  
Laboratory Analytical Results - Soils

Laboratory Parameters (Units)	RCL	MW-1 7-9'	MW-3 5-7'	MW-4 9-11'	MW-5 3-5'	MW-6 7-9'
Date Sampled	---	12/3/98	12/2/98	12/2/98	2/16/99	2/16/99
Solids (%)	---	85.5	91.0	91.5	88.0	76.0
GRO (mg/kg)	100	17	<1.3	18	7.4	<1.3
Benzene (ug/kg)	5.5	<25	<25	<25	<25	<25
Toluene (ug/kg)	1,500	<25	<25	<25	<25	<25
Ethylbenzene (ug/kg)	2,900	<25	<25	79	<25	<25
MTBE (ug/kg)	---	<25	<25	<25	<25	<25
Xylenes, Total (ug/kg)	4,100	<50	<50	183	<50	<50
1,3,5-Trimethylbenzene (ug/kg)	---	120	<50	400	34	<25
1,2,4-Trimethylbenzene (ug/kg)	---	130	<25	970	33	<25

## Abbreviations:

ug/kg = micrograms per kilogram = parts per billion (ppb)  
mg/kg = milligrams per kilogram = parts per million (ppm)

Shading indicates parameter concentration above NR 720 RCL

Laboratory Parameters (units)	NR 720 RCL	CB-1 @ 2-4'	CB-2 @ 2-4'	CB-3 @ 2-4'	CB-4 @ 2-4'	CB-5 @ 2-4'	CB-6 @ 2-4'
Solids (%)	--	94.6	99.6	91.4	94.1	91.5	91.3
Lead (mg/kg)	50	1,690	4.8	8.3	74.4	5.1	51.2
Benzene (ug/kg)	5.5	1,700	56	<25	<25	78	<25
Toluene (ug/kg)	1,500	310	<25	<25	68	550	71
Ethylbenzene (ug/kg)	2,900	400	310	<25	40	250	57
MTBE (ug/kg)	--	380	<25	<25	<25	<25	<25
Xylenes, Total (ug/kg)	4,100	1,240	1,580	<25	195	1,580	279
1,2,4,TMB (ug/kg)	--	350	1,000	<25	120	970	280
1,3,5,TMB (ug/kg)	--	210	320	<25	29	270	140

Notes: 1) Shading indicates parameter concentration above NR 720 RCL.

Table 6  
Groundwater Analytical Results  
CCP-Poynette

Parameter (µg/l)	NR 140 ES	MW-1	MW-2	MW-3	MW-4	MW-4A	MW-5	MW-6	Field Blank
GRO (12/98)	—	<30	12,000	82	4,000	260	NT	NT	<30
(2/99)		<30	61	<30	1,700	<30	<30	<30	<30
(6/99)		<30	43	<30	700	<30	<30	<30	<30
(9/99)		<30	77	<30	1,800	<30	<30	<30	<30
DRO (12/98)	—	120	3,700	130	1,600	1,100	NT	NT	NT
(2/99)		290	160	<26	840	180	<28	<26	NT
(6/99)		38	110	27	280	76	<26	55	NT
(9/99)		42	44	<26	580	<27	<27	<27	NT
benzene (12/98)	5	<0.20	350	0.80	520	11	NT	NT	<0.20
(2/99)		<0.20	0.40	<0.20	95	<0.20	<0.30	<0.30	<0.20
(6/99)		<0.20	0.20	<0.20	62	<0.20	<0.20	<0.20	<0.20
(9/99)		<0.20	1.8	<0.20	190	<0.20	<0.20	<0.20	<0.20
ethylbenzene (12/98)	700	<0.30	580	<0.30	42	1.4	NT	NT	<0.30
(2/99)		<0.30	<0.30	<0.30	6.4	<0.30	0.30	0.40	<0.30
(6/99)		<0.30	0.70	<0.30	18	<0.30	<0.30	<0.30	<0.30
(9/99)		<0.30	2.5	<0.30	38	<0.30	<0.30	<0.30	<0.30
MTBE (12/98)	60	<0.20	28	5.5	36	1.1	NT	NT	<0.20
(2/99)		<0.20	<0.20	<0.20	4.9	<0.20	<0.20	<0.20	<0.20
(6/99)		<0.20	<0.20	<0.20	6.6	<0.20	<0.20	<0.20	<0.20
(9/99)		<0.20	<0.20	<0.20	12	<0.20	<0.20	<0.20	<0.20
toluene (12/98)	343	<0.20	120	0.90	18	1.2	NT	NT	1.2
(2/99)		<0.20	<0.20	<0.20	3.9	<0.20	0.60	1.0	0.90
(6/99)		<0.20	<0.20	<0.20	2.0	<0.20	<0.20	<0.20	3.2
(9/99)		0.90	0.20	<0.20	4.5	<0.20	<0.20	0.50	<0.20
1,2,4-tmb (12/98)	—	1.4	1,200	1.3	340	2.5	NT	NT	<0.30
(2/99)		<0.30	5.1	<0.30	65	<0.30	<0.60	<0.60	<0.30
(6/99)		<0.30	3.6	<0.30	28	<0.30	<0.30	<0.30	0.90
(9/99)		<0.30	6.3	<0.30	20	<0.30	<0.30	<0.30	<0.30
1,3,5-tmb (12/98)	—	0.70	350	<0.30	170	10	NT	NT	<0.30
(2/99)		<0.30	3.2	<0.30	44	<0.30	<0.30	<0.30	<0.30
(6/99)		<0.30	1.6	<0.30	14	<0.30	<0.30	<0.30	<0.30
(9/99)		<0.30	3.1	<0.30	18	<0.30	<0.30	<0.30	<0.30
total xylenes (12/98)	620	<0.90	3,900	2.0	158	7.5	NT	NT	<0.90
(2/99)		<0.90	<0.90	<0.90	14.1	<0.90	1.6	1.8	<0.90
(6/99)		<0.90	4.7	<0.90	66.0	<0.90	<0.90	<0.90	<0.90
(9/99)		<0.90	9.4	<0.90	60	<0.90	<0.90	<0.90	<0.90
Naphthalene (12/98)	40	NT	NT	NT	NT	NT	NT	NT	NT
(2/99)		<1.7	<1.7	<1.7	12	<1.7	<1.1	<1.1	NT
Lead (12/98)	15	NT	NT	NT	NT	NT	NT	NT	NT
(2/99)		<1	<1	<1	<1	<1	NT	<1	NT

Notes: mg/l milligrams per liter      µg/l micrograms per liter (1,000 µg/l = 1 mg/l)  
 DRO diesel range organics      MTBE methyl tertiary butyl ether  
 ES NR 140 groundwater enforcement standard

GRO gasoline range organics  
 NT-- not tested

Shading indicates compound concentration exceeds NR 140 ES during the most recent sampling event

**Table 1**  
**CCP-Poynette**  
**Laboratory Analytical Results - Geoprobe® Soil Borings**  
**4/10/00**

Laboratory Parameters (units)	NR 720 RCL	CB-1 @ 2-4'	CB-2 @ 2-4'	CB-3 @ 2-4'	CB-4 @ 2-4'	CB-5 @ 2-4'	CB-6 @ 2-4'
Solids (%)	-	94.6	99.6	91.4	94.1	91.5	91.3
Lead (mg/kg)	50	1,690	4.8	8.3	74.4	5.1	51.2
Benzene (ug/kg)	5.5	1,700	56	<25	<25	78	<25
Toluene (ug/kg)	1,500	310	<25	<25	68	550	71
Ethylbenzene (ug/kg)	2,900	400	310	<25	40	250	57
MTBE (ug/kg)	-	380	<25	<25	<25	<25	<25
Xylenes, Total (ug/kg)	4,100	1,240	1,580	<25	195	1,580	279
1,2,4,TMB (ug/kg)	-	350	1,000	<25	120	970	280
1,3,5,TMB (ug/kg)	-	210	320	<25	29	270	140

Abbreviations: ug/kg = micrograms per kilogram      mg/kg = milligrams per kilogram  
 nt = not tested      GRO = gasoline range organics  
 MTBE = methyl-tertiary-butyl-ether      TMB = trimethylbenzene  
 RCL = residual contaminant level      na = not applicable

Notes: 1) Shading indicates parameter concentration above NR 720 RCL.

Figure 9: Groundwater Elevations (June 25, 1999)






TABLE 7  
Depth to Groundwater Measurements & Water Table Elevations  
CCP- POYNETTE

Monitoring Well	PVC Elevation (msl)		Dec. 3, 1998	Feb. 16, 1999	June 25, 1999	Sept. 10, 1999
MW-1	836.42	Depth to Water (feet)	4.72	4.61	4.12	4.22
		Water Table Elevation (msl)	831.70	831.81	832.30	832.20
MW-2	835.63	Depth to Water (feet)	5.05	4.57	NT	4.65
		Water Table Elevation (msl)	830.58	831.06	NT	830.98
MW-3	835.05	Depth to Water (feet)	5.86	5.06	5.37	5.60
		Water Table Elevation (msl)	829.19	829.99	829.68	829.45
MW-4	834.17	Depth to Water (feet)	5.01	4.32	4.56	4.73
		Water Table Elevation (msl)	829.16	829.85	829.61	829.44
MW-4A	834.05	Depth to Water (feet)	2.43	1.97	1.98	2.07
		Water Table Elevation (msl)	831.62	832.08	832.07	831.98
MW-5	832.30	Depth to Water (feet)	NA	3.97	3.90	4.10
		Water Table Elevation (msl)	NA	828.33	828.40	828.20
MW-6	835.23	Depth to Water (feet)	NA	4.99	5.66	5.71
		Water Table Elevation (msl)	NA	830.24	829.57	829.52

Notes: TOC = top-of-casing  
BOS = bottom-of-(well) screen  
msl = mean sea level

SOUTH  
B  
ELEVATION IN FEET ABOVE MSL



NORTH  
B'  
ELEVATION IN FEET ABOVE MSL

GEOLOGIC CROSS SECTION B - B'  
118 SOUTH MAIN STREET  
COOP COUNTRY PARTNERS  
118 South Main Street (County Highway Q)  
Poynette, Wisconsin

REVISIONS:  
DATE: MAR 1988  
DRAWN: SGB  
CHECKED: BJC  
APPROVED: WMB  
FIGURE 4  
#970094.3

RESOURCE ENGINEERING ASSOCIATES, INC.  
Resource Engineering Associates, Inc.  
8505 University Green  
Suite 200  
Middleton, Wisconsin 53562-2507  
P: 608-831-8563 F: 608-831-8564




WEST A  
ELEVATION IN FEET ABOVE MSL  
840  
835  
830  
825  
820  
815  
810  
805  
800

- 1) All dimensions and locations are approximate and are based on limited field measurements and aerial photographs.  
2) See Figures 1 & 2 for site location and overall view of site.  
3) See Figure 4 for Geological Cross Section B-B' (South-North).  
4) Groundwater elevations collected by REA on February 16, 1988.  
5) Site elevation referenced to mean sea level (MSL).



SCALE:  
VERTICAL: 1" = 5'  
HORIZONTAL: 1" = 20'

LEGEND:  
DEPTH TO GROUNDWATER (10-1-1988)  
(SHALLOW WELL)  
DEPTH TO GROUNDWATER (10-1-1988)  
(DEEP PIEZOMETER WELL)  
MONITORING WELL SCREEN (10 FOOT LONG  
SLOTTED PVC PIPE (10" SLOTS))  
STRATIGRAPHIC BOUNDARY LINE  
INDISPERIMENT  
BEDROCK



EAST A'  
ELEVATION IN FEET ABOVE MSL  
840  
835  
830  
825  
820  
815  
810  
805  
800

GEOLOGICAL CROSS SECTION A - A'  
118 SOUTH MAIN STREET  
(NOT TO SCALE)



GEOLOGIC CROSS SECTION A - A'  
118 SOUTH MAIN STREET  
COOP COUNTRY PARTNERS  
118 South Main Street (County Highway Q)  
Poynette, Wisconsin

**REA** **RESOURCE ENGINEERING ASSOCIATES, INC.**  
Resource Engineering Associates, Inc.  
8505 University Green  
Suite 200  
Middleton, Wisconsin 53582-2507  
P: 608-831-6563 F: 608-831-6564

REVISIONS:

Date: MAR 1988  
Drawn: SSG  
Checked: BJC  
Approved: WMB  
PROJECT/OWNER  
#970094.3  
FIGURE 3

June 15, 2001

Mr. Mike Paulcheck  
Director of Public Works  
Village of Poynette  
P.O. Box 95, 106 South Main Street  
Poynette, WI 53955

RE: Potential Petroleum Contaminated Groundwater in Main Street Right-of-Way


Dear Mr. Paulcheck:

Resource Engineering Associates, Inc. (REA), on behalf of Coop Country Partners, is sending this letter as required by NR 726.05 (2) (b) 4 to notify you of potential environmental concerns caused by the release of petroleum products at the former CSI gasoline station located at 118 S. Main Street in Poynette, Wisconsin.

Based on data collected during remedial investigation activities conducted between July 1998 and April 2000, it appears likely that groundwater containing petroleum compounds occurs beneath the Main Street right-of-way (ROW) near the former gasoline station at 118 S. Main Street.

If you have any questions concerning this notice, or site conditions in general, feel free to call me at (608) 831-6563.

Sincerely,



William W. Buckingham, P.E.  
Senior Engineer

June 15, 2001

Mr. Dennis Linn  
Administrator  
Village of Poynette  
P.O. Box 95, 106 South Main Street  
Poynette, WI 53955

RE: Potential Petroleum Contaminated Groundwater in Main Street Right-of-Way


Dear Mr. Linn:

Resource Engineering Associates, Inc. (REA), on behalf of Coop Country Partners, is sending this letter as required by NR 726.05 (2) (b) 4 to notify you of potential environmental concerns caused by the release of petroleum products at the former CSI gasoline station located at 118 S. Main Street in Poynette, Wisconsin.

Based on data collected during remedial investigation activities conducted between July 1998 and April 2000, it appears likely that groundwater containing petroleum compounds occurs beneath the Main Street right-of-way (ROW) near the former gasoline station at 118 S. Main Street.

If you have any questions concerning this notice, or site conditions in general, feel free to call me at (608) 831-6563.

Sincerely,



William W. Buckingham, P.E.  
Senior Engineer